

Coordonate stereo pentru limitele fondului forestier proprietate publică a statului
din Ocolul silvic Târnița

| Nr. crt. | Coordonate | | Nr. crt. | Coordonate | | Nr. crt. | Coordonate | |
|----------|-------------|-------------|----------|-------------|-------------|----------|-------------|-------------|
| | X | Y | | X | Y | | X | Y |
| 18415 | 391326.2746 | 313811.1672 | | | | | | |
| 18416 | 391350.9167 | 313821.9765 | | | | | | |
| 18417 | 391362.7318 | 313817.9665 | 18477 | 389724.2888 | 318432.4885 | 18539 | 388175.3389 | 303849.5346 |
| 18418 | 391371.3405 | 313806.1553 | 18478 | 389780.2113 | 318413.9430 | 18540 | 388184.2609 | 303832.9570 |
| 18419 | 391376.3131 | 313803.0938 | 18479 | 389887.7282 | 318417.6479 | 18541 | 388217.4836 | 303758.3678 |
| | | | 18480 | 389927.3019 | 318467.0728 | 18542 | 388311.2578 | 303684.8578 |
| | | | 18481 | 390014.2855 | 318571.7931 | 18543 | 388316.4210 | 303664.7889 |
| 18420 | 389939.5920 | 314058.8785 | 18482 | 390047.3056 | 318645.1384 | 18544 | 388321.5164 | 303558.7159 |
| 18421 | 390024.4291 | 314089.3852 | 18483 | 390064.6250 | 318694.1655 | 18545 | 388379.7952 | 303440.2021 |
| 18422 | 390078.7912 | 314091.4118 | 18484 | 390105.5668 | 318755.4168 | 18546 | 388472.1950 | 303141.5714 |
| 18423 | 390133.3906 | 314242.9163 | 18485 | 390125.9683 | 318824.1781 | 18547 | 388682.1307 | 303048.7838 |
| 18424 | 390063.7278 | 314387.6846 | 18486 | 390264.8954 | 318828.1092 | 18548 | 388693.5335 | 303029.8626 |
| 18425 | 390019.9236 | 314396.1203 | 18487 | 390342.7418 | 318872.6952 | 18549 | 388695.3341 | 303013.1949 |
| 18426 | 389974.3145 | 314366.4625 | 18488 | 390335.2145 | 318918.5211 | 18550 | 388680.5306 | 302906.9799 |
| 18427 | 390018.0000 | 314291.0684 | 18489 | 390303.4454 | 318917.4625 | 18551 | 388717.7394 | 302891.6641 |
| 18428 | 389935.2009 | 314119.6816 | 18490 | 390208.6788 | 318936.2663 | 18552 | 388760.7216 | 302859.0580 |
| 18429 | 389947.7939 | 314111.3693 | 18491 | 390044.9935 | 318968.9332 | 18553 | 388767.7250 | 302846.4624 |
| 18430 | 389942.3948 | 314081.3849 | 18492 | 390006.4514 | 319007.8702 | 18554 | 388817.9175 | 302850.4787 |
| 18431 | 389934.9059 | 314074.9569 | 18493 | 389952.9718 | 318934.6209 | 18555 | 388915.1771 | 302882.8160 |
| 18432 | 389939.5920 | 314058.8785 | 18494 | 389992.1630 | 318885.7496 | 18556 | 389008.6872 | 302935.6255 |
| | | | 18495 | 389992.1630 | 318840.0624 | 18557 | 389053.5874 | 302954.6951 |
| 18433 | 386444.9247 | 312432.2515 | 18496 | 389877.2535 | 318720.8185 | 18558 | 389166.0046 | 302987.2734 |
| 18434 | 386478.6958 | 312434.6981 | 18497 | 389805.5005 | 318668.0738 | 18559 | 389201.5397 | 302994.4804 |
| 18435 | 386477.6806 | 312468.1951 | 18498 | 389748.7716 | 318549.2141 | 18560 | 389310.4044 | 303039.3803 |
| 18436 | 386492.8755 | 312497.8045 | 18499 | 389723.6141 | 318456.4803 | 18561 | 389384.2353 | 303096.8110 |
| 18437 | 386501.3332 | 312551.1856 | 18500 | 389721.0483 | 318437.9625 | 18562 | 389387.8382 | 303131.7405 |
| 18438 | 386496.9883 | 312590.7313 | 18501 | 389724.2888 | 318432.4885 | 18563 | 389432.9446 | 303251.6189 |
| 18439 | 386484.1827 | 312643.3152 | | | | 18564 | 389385.4275 | 303250.4344 |
| 18440 | 386421.9909 | 312663.7671 | | | | 18565 | 389401.0527 | 303355.6526 |
| 18441 | 386413.9308 | 312651.8817 | | | | 18566 | 389454.1099 | 303431.9006 |
| 18442 | 386425.9364 | 312641.4261 | 18502 | 385078.2775 | 304267.9338 | 18567 | 389546.1525 | 303497.5035 |
| 18443 | 386429.2996 | 312634.5593 | 18503 | 385235.4104 | 304154.4469 | 18568 | 389591.1228 | 303634.3184 |
| 18444 | 386426.7734 | 312595.5565 | 18504 | 385405.3167 | 304119.0885 | 18569 | 389662.9988 | 303746.6580 |
| 18445 | 386404.2395 | 312547.4229 | 18505 | 385548.0211 | 304156.1151 | 18570 | 389780.1865 | 303797.3914 |
| 18446 | 386407.4832 | 312515.3973 | 18506 | 385913.9415 | 304131.0067 | 18571 | 389819.8715 | 303799.3074 |
| 18447 | 386439.6940 | 312494.0665 | 18507 | 386097.8055 | 303938.6450 | 18572 | 389838.0313 | 303857.7452 |
| 18448 | 386448.0225 | 312466.4279 | 18508 | 386403.6262 | 303946.7151 | 18573 | 389834.9681 | 303863.8760 |
| 18449 | 386441.3617 | 312446.5853 | 18509 | 386841.7298 | 304121.7215 | 18574 | 389818.1934 | 303860.3721 |
| 18450 | 386444.9247 | 312432.2515 | 18510 | 386863.8387 | 304131.9223 | 18575 | 389803.3143 | 303860.3721 |
| | | | 18511 | 386904.3526 | 304173.2141 | 18576 | 389800.6889 | 303876.2854 |
| 18451 | 386339.3886 | 308347.0801 | 18512 | 386928.4551 | 304229.7041 | 18577 | 389842.7707 | 303955.7343 |
| 18452 | 386353.7289 | 308347.0801 | 18513 | 386945.8940 | 304247.2636 | 18578 | 389873.5490 | 303946.8288 |
| 18453 | 386407.5064 | 308353.9495 | 18514 | 387013.2105 | 304222.8729 | 18579 | 389934.6960 | 304064.4599 |
| 18454 | 386462.6714 | 308366.6845 | 18515 | 387090.4629 | 304193.4882 | 18580 | 389930.6416 | 304125.9722 |
| 18455 | 386363.2053 | 308457.6514 | 18516 | 387160.3364 | 304204.1448 | 18581 | 389949.7767 | 304161.4141 |
| 18456 | 386301.4513 | 308518.3371 | 18517 | 387197.4280 | 304205.9713 | 18582 | 389963.0561 | 304170.2750 |
| 18457 | 386219.6706 | 308592.2976 | 18518 | 387268.3386 | 304192.7027 | 18583 | 390049.4990 | 304219.0863 |
| 18458 | 386154.9213 | 308651.8411 | 18519 | 387332.8493 | 304195.6043 | 18584 | 390057.7244 | 304221.3304 |
| 18459 | 386150.0733 | 308649.3597 | 18520 | 387359.6137 | 304201.2653 | 18585 | 390104.6698 | 304195.4564 |
| 18460 | 386140.0139 | 308647.1573 | 18521 | 387413.3073 | 304201.2653 | 18586 | 390099.2780 | 304169.1064 |
| 18461 | 386126.4964 | 308644.9550 | 18522 | 387470.7832 | 304192.3005 | 18587 | 389990.2672 | 304046.1749 |
| 18462 | 386105.2209 | 308637.1671 | 18523 | 387490.5138 | 304183.7352 | 18588 | 389901.9885 | 303957.4660 |
| 18463 | 386097.6387 | 308630.8965 | 18524 | 387526.0401 | 304184.2704 | 18589 | 389883.5907 | 303881.2739 |
| 18464 | 386092.0228 | 308623.5897 | 18525 | 387533.5801 | 304179.4133 | 18590 | 389881.2117 | 303836.3513 |
| 18465 | 386085.2838 | 308620.8597 | 18526 | 387545.7654 | 304149.0759 | 18591 | 389885.9698 | 303824.6062 |
| 18466 | 386071.3244 | 308623.2686 | 18527 | 387576.1520 | 304120.7169 | 18592 | 389892.7896 | 303824.6062 |
| 18467 | 386034.2825 | 308642.3856 | 18528 | 387602.0334 | 304119.2471 | 18593 | 389904.2088 | 303832.5436 |
| 18468 | 386018.3358 | 308643.3382 | 18529 | 387647.7803 | 304130.9777 | 18594 | 389979.0636 | 303953.9014 |
| 18469 | 386006.5975 | 308634.8796 | 18530 | 387748.5688 | 304124.6649 | 18595 | 390112.1710 | 304059.7347 |
| 18470 | 386339.3886 | 308347.0801 | 18531 | 387770.3983 | 304120.5698 | 18596 | 390176.2569 | 304122.9524 |
| | | | 18532 | 387782.6538 | 304113.5048 | 18597 | 390158.9409 | 304159.6581 |
| 18471 | 386339.1227 | 308347.0801 | 18533 | 387831.5436 | 304051.7343 | 18598 | 390202.9296 | 304240.0428 |
| 18472 | 386353.7289 | 308347.0801 | 18534 | 387965.4376 | 303965.5096 | 18599 | 390202.7896 | 304265.1917 |
| 18473 | 386462.6714 | 308366.6845 | 18535 | 388019.1254 | 303914.3906 | 18600 | 390184.4002 | 304261.8195 |
| 18474 | 386154.9213 | 308651.8411 | 18536 | 388095.1999 | 303896.9062 | 18601 | 390210.8840 | 304389.7430 |
| 18475 | 386006.5975 | 308634.8796 | 18537 | 388123.7134 | 303888.0492 | 18602 | 390240.4204 | 304472.6214 |
| 18476 | 386339.1227 | 308347.0801 | 18538 | 388145.4748 | 303877.8708 | 18603 | 390297.1387 | 304495.8847 |
| | | | | | | 18604 | 390408.3026 | 304695.9218 |

U.P. VI Vf. lui Stan parc. 105-114,
116-127, 134-151, 153-162, 172-182,
189-202, 208, 212%-235

Anexa nr.1 (continuare)

| Nr. crt. | Coordonate | | Nr. crt. | Coordonate | | Nr. crt. | Coordonate | |
|----------|-------------|-------------|----------|-------------|-------------|----------|-------------|-------------|
| | X | Y | | X | Y | | X | Y |
| 18605 | 390414.6241 | 304735.1186 | 18672 | 391529.5021 | 305501.6297 | 18739 | 393972.1428 | 307499.9098 |
| 18606 | 390398.9106 | 304763.8930 | 18673 | 391566.6317 | 305495.2154 | 18740 | 393984.2144 | 307511.2147 |
| 18607 | 390393.0017 | 304759.7673 | 18674 | 391594.2517 | 305495.2154 | 18741 | 394060.0583 | 307574.0090 |
| 18608 | 390369.7777 | 304724.2829 | 18675 | 391612.6980 | 305498.9421 | 18742 | 394084.1474 | 307578.7395 |
| 18609 | 390336.0640 | 304707.0795 | 18676 | 391644.8800 | 305510.7702 | 18743 | 394072.3982 | 307602.8990 |
| 18610 | 390322.5971 | 304707.0795 | 18677 | 391696.7898 | 305521.8064 | 18744 | 394061.0548 | 307638.2092 |
| 18611 | 390314.4902 | 304717.3947 | 18678 | 391715.3929 | 305520.5729 | 18745 | 394064.9303 | 307651.3640 |
| 18612 | 390329.1938 | 304772.1342 | 18679 | 391743.3535 | 305507.3392 | 18746 | 394057.1016 | 307682.3961 |
| 18613 | 390362.2355 | 304823.6230 | 18680 | 391798.6802 | 305566.9538 | 18747 | 394048.9176 | 307686.2239 |
| 18614 | 390447.4417 | 304872.0697 | 18681 | 391838.1292 | 305620.5125 | 18748 | 394015.2602 | 307687.8974 |
| 18615 | 390454.1757 | 304873.5826 | 18682 | 391864.0604 | 305654.0483 | 18749 | 393950.4130 | 307727.4796 |
| 18616 | 390468.0552 | 304865.3313 | 18683 | 391877.1432 | 305672.4692 | 18750 | 393931.9250 | 307700.0988 |
| 18617 | 390502.5295 | 304816.4228 | 18684 | 391881.9323 | 305678.6196 | 18751 | 393962.5510 | 307684.8648 |
| 18618 | 390514.8438 | 304819.2988 | 18685 | 391891.0052 | 305687.0014 | 18752 | 393963.7653 | 307674.5863 |
| 18619 | 390534.8357 | 304844.9217 | 18686 | 391921.5518 | 305709.1384 | 18753 | 393905.4681 | 307617.3318 |
| 18620 | 390568.9245 | 304943.9519 | 18687 | 391975.1564 | 305739.9230 | 18754 | 393805.5221 | 307753.0083 |
| 18621 | 390577.7855 | 304962.5832 | 18688 | 392022.2335 | 305788.5118 | 18755 | 393775.6177 | 307719.5400 |
| 18622 | 390608.6021 | 304982.9037 | 18689 | 392075.5967 | 305906.7586 | 18756 | 393759.6265 | 307676.9272 |
| 18623 | 390610.9952 | 305001.0428 | 18690 | 392086.6451 | 305928.1033 | 18757 | 393806.7625 | 307560.0327 |
| 18624 | 390595.0259 | 305040.3693 | 18691 | 392122.8003 | 305973.5032 | 18758 | 393657.4725 | 307499.0822 |
| 18625 | 390592.8457 | 305079.5236 | 18692 | 392157.2925 | 305996.5572 | 18759 | 393517.3573 | 307516.1216 |
| 18626 | 390602.0530 | 305098.0740 | 18693 | 392245.7381 | 306038.5655 | 18760 | 393420.2745 | 307494.9177 |
| 18627 | 390616.6745 | 305109.5800 | 18694 | 392280.0527 | 306063.5258 | 18761 | 393417.4795 | 307406.7346 |
| 18628 | 390635.7763 | 305109.5800 | 18695 | 392300.3186 | 306086.3469 | 18762 | 393374.4920 | 307371.5420 |
| 18629 | 390689.5972 | 305098.6897 | 18696 | 392327.7112 | 306124.9148 | 18763 | 393182.8951 | 307385.0884 |
| 18630 | 390718.9485 | 305084.4331 | 18697 | 392390.3404 | 306183.9548 | 18764 | 393069.4511 | 307297.0310 |
| 18631 | 390735.9285 | 305089.2191 | 18698 | 392467.7966 | 306243.2628 | 18765 | 393032.8853 | 307191.5975 |
| 18632 | 390749.9872 | 305104.1095 | 18699 | 392531.4708 | 306284.7709 | 18766 | 393022.9991 | 307184.5221 |
| 18633 | 390754.0313 | 305133.7953 | 18700 | 392567.2565 | 306297.5040 | 18767 | 393015.6621 | 307185.8143 |
| 18634 | 390766.4978 | 305159.7746 | 18701 | 392633.5467 | 306315.6222 | 18768 | 392972.5811 | 307235.5471 |
| 18635 | 390777.8806 | 305170.2154 | 18702 | 392694.6877 | 306338.9950 | 18769 | 392906.8983 | 307195.1271 |
| 18636 | 390785.3631 | 305172.2205 | 18703 | 392718.1403 | 306354.5455 | 18770 | 392899.7407 | 307158.2875 |
| 18637 | 390796.3232 | 305173.3122 | 18704 | 392751.0509 | 306397.9535 | 18771 | 392894.8687 | 307154.7153 |
| 18638 | 390831.4499 | 305171.7830 | 18705 | 392757.7336 | 306403.7509 | 18772 | 392845.8267 | 307154.7153 |
| 18639 | 388175.3389 | 303849.5346 | 18706 | 392808.0824 | 306436.5092 | 18773 | 392819.9250 | 307086.0362 |
| 18640 | 388184.2609 | 303832.9570 | 18707 | 392851.6887 | 306454.9991 | 18774 | 392781.2544 | 307076.3501 |
| 18641 | 388217.4836 | 303758.3678 | 18708 | 392878.1779 | 306461.9350 | 18775 | 392746.1545 | 307048.0951 |
| 18642 | 388311.2578 | 303684.8578 | 18709 | 392926.4472 | 306477.8826 | 18776 | 392583.9927 | 306971.4480 |
| 18643 | 388316.4210 | 303664.7889 | 18710 | 392951.3646 | 306479.7955 | 18777 | 392600.1493 | 306795.0291 |
| 18644 | 388321.5164 | 303558.7159 | 18711 | 392972.0549 | 306476.5722 | 18778 | 392753.1803 | 306803.5995 |
| 18645 | 388379.7952 | 303440.2021 | 18712 | 392991.6113 | 306480.1424 | 18779 | 392856.8654 | 306916.1733 |
| 18646 | 388472.1950 | 303141.5714 | 18713 | 393023.9433 | 306496.0255 | 18780 | 393003.8849 | 306930.9449 |
| 18647 | 388682.1307 | 303048.7838 | 18714 | 393059.3619 | 306520.4345 | 18781 | 393105.8052 | 306984.9761 |
| 18648 | 388693.5335 | 303029.8626 | 18715 | 393112.7496 | 306565.2401 | 18782 | 392919.3280 | 307004.0339 |
| 18649 | 388695.3341 | 303013.1949 | 18716 | 393170.1935 | 306630.6257 | 18783 | 392953.8492 | 307040.7032 |
| 18650 | 388680.5306 | 302906.9799 | 18717 | 393202.0609 | 306669.8174 | 18784 | 393096.4998 | 307040.7032 |
| 18651 | 388717.7394 | 302891.6641 | 18718 | 393229.9563 | 306697.6771 | 18785 | 393211.9488 | 307069.0982 |
| 18652 | 388760.7216 | 302859.0580 | 18719 | 393240.2014 | 306705.5457 | 18786 | 393248.7004 | 307129.6125 |
| 18653 | 388767.7250 | 302846.4624 | 18720 | 393254.8525 | 306714.2737 | 18787 | 393329.6419 | 307103.0128 |
| 18654 | 388817.9175 | 302850.4787 | 18721 | 393322.3989 | 306743.0912 | 18788 | 393304.7588 | 307029.0860 |
| 18655 | 388915.1771 | 302882.8160 | 18722 | 393371.6110 | 306771.4436 | 18789 | 393313.9084 | 306877.1530 |
| 18656 | 389008.6872 | 302935.6255 | 18723 | 393399.7487 | 306802.9808 | 18790 | 393332.0220 | 306831.6902 |
| 18657 | 389053.5874 | 302954.6951 | 18724 | 393427.4760 | 306865.6392 | 18791 | 393309.9636 | 306769.7519 |
| 18658 | 389166.0046 | 302987.2734 | 18725 | 393475.4355 | 306992.8974 | 18792 | 393257.3601 | 306867.6820 |
| 18659 | 389201.5397 | 302994.4804 | 18726 | 393494.7105 | 307029.9095 | 18793 | 393262.9875 | 306890.5696 |
| 18660 | 389310.4044 | 303039.3803 | 18727 | 393533.4083 | 307066.9642 | 18794 | 393249.4202 | 306912.3537 |
| 18661 | 389384.2353 | 303096.8110 | 18728 | 393574.4430 | 307091.2596 | 18795 | 393194.1470 | 306947.1384 |
| 18662 | 389387.8382 | 303131.7405 | 18729 | 393629.3769 | 307131.7424 | 18796 | 393186.1416 | 306946.5116 |
| 18663 | 389432.9446 | 303251.6189 | 18730 | 393651.7106 | 307140.6070 | 18797 | 393088.5558 | 306840.1815 |
| 18664 | 389385.4275 | 303250.4344 | 18731 | 393668.9553 | 307155.1737 | 18798 | 393038.0845 | 306773.8636 |
| 18665 | 389401.0527 | 303355.6526 | 18732 | 393696.5685 | 307193.6240 | 18799 | 392989.8464 | 306788.5074 |
| 18666 | 389454.1099 | 303431.9006 | 18733 | 393734.5867 | 307243.0911 | 18800 | 392902.8124 | 306773.7825 |
| 18667 | 389546.1525 | 303497.5035 | 18734 | 393792.1211 | 307286.7181 | 18801 | 392866.5871 | 306739.7199 |
| 18668 | 389591.1228 | 303634.3184 | 18735 | 393815.9925 | 307306.2100 | 18802 | 392850.6716 | 306746.3896 |
| 18669 | 389662.9988 | 303746.6580 | 18736 | 393886.7128 | 307372.0695 | 18803 | 392751.5369 | 306712.4405 |
| 18670 | 389780.1865 | 303797.3914 | 18737 | 393919.1027 | 307412.9397 | 18804 | 392660.5834 | 306646.0050 |
| 18671 | 389819.8715 | 303799.3074 | 18738 | 393938.1104 | 307450.5076 | 18805 | 392575.0263 | 306577.3807 |

Anexa nr.1 (continuare)

| Nr. crt. | Coordonate | | Nr. crt. | Coordonate | | Nr. crt. | Coordonate | |
|----------|-------------|-------------|----------|-------------|-------------|----------|-------------|-------------|
| | X | Y | | X | Y | | X | Y |
| 18806 | 392505.1594 | 306543.8577 | 18873 | 392110.1079 | 306278.3671 | 18940 | 392643.3892 | 307702.7927 |
| 18807 | 392505.1594 | 306533.2263 | 18874 | 392075.4904 | 306293.8831 | 18941 | 392663.6354 | 307818.0665 |
| 18808 | 392527.7623 | 306511.7809 | 18875 | 391921.1424 | 306229.3848 | 18942 | 392970.3844 | 307986.5865 |
| 18809 | 392522.6004 | 306493.5913 | 18876 | 391842.4374 | 306155.9498 | 18943 | 393169.8774 | 308131.1539 |
| 18810 | 392466.2234 | 306493.5913 | 18877 | 391831.7865 | 306115.8735 | 18944 | 393178.0193 | 308056.6591 |
| 18811 | 392448.2719 | 306531.2728 | 18878 | 391806.9663 | 306095.3874 | 18945 | 393199.6042 | 308009.1008 |
| 18812 | 392447.4238 | 306588.1560 | 18879 | 391761.4153 | 306086.3198 | 18946 | 393269.9572 | 307927.8755 |
| 18813 | 392467.9442 | 306638.3920 | 18880 | 391702.4719 | 306104.1876 | 18947 | 393233.6253 | 307881.0414 |
| 18814 | 392537.8971 | 306708.0164 | 18881 | 391658.5514 | 306153.2601 | 18948 | 393167.9172 | 307856.5938 |
| 18815 | 392531.8089 | 306727.6340 | 18882 | 391630.2632 | 306146.1937 | 18949 | 393115.7643 | 307870.7406 |
| 18816 | 392498.4646 | 306756.3739 | 18883 | 391609.5321 | 306123.1329 | 18950 | 393047.7080 | 307838.1182 |
| 18817 | 392503.5955 | 306767.7619 | 18884 | 391445.6436 | 306103.8939 | 18951 | 393013.3476 | 307782.2958 |
| 18818 | 392515.3616 | 306772.6810 | 18885 | 391463.3395 | 306055.5647 | 18952 | 392981.3736 | 307627.0443 |
| 18819 | 392538.9151 | 306765.9038 | 18886 | 391631.4905 | 305985.1266 | 18953 | 392918.0689 | 307569.0311 |
| 18820 | 392554.8287 | 306770.7905 | 18887 | 391677.1125 | 305947.3839 | 18954 | 392931.3913 | 307489.4630 |
| 18821 | 392560.6448 | 306787.0895 | 18888 | 391676.6197 | 305874.6633 | 18955 | 392973.0784 | 307444.4465 |
| 18822 | 392558.7818 | 306831.2277 | 18889 | 391696.4016 | 305857.1742 | 18956 | 392964.0420 | 307406.7427 |
| 18823 | 392564.8962 | 306854.1762 | 18890 | 391761.1549 | 305906.6599 | 18957 | 393076.8692 | 307366.4018 |
| 18824 | 392557.0179 | 306885.0115 | 18891 | 391775.4665 | 305979.2632 | 18958 | 393110.1537 | 307404.6959 |
| 18825 | 392534.2468 | 306906.0917 | 18892 | 391798.5085 | 306004.8050 | 18959 | 393152.5476 | 307525.6130 |
| 18826 | 392468.5303 | 306917.1004 | 18893 | 391854.9795 | 306013.5080 | 18960 | 393152.5476 | 307582.1137 |
| 18827 | 392461.0858 | 306927.9082 | 18894 | 391871.5367 | 305999.9042 | 18961 | 393190.1115 | 307690.8488 |
| 18828 | 392459.8229 | 307006.8069 | 18895 | 391857.7843 | 305925.7502 | 18962 | 393241.0362 | 307742.1984 |
| 18829 | 392445.8863 | 307039.0966 | 18896 | 391813.3335 | 305928.2483 | 18963 | 393303.5772 | 307773.8005 |
| 18830 | 392398.2745 | 307093.0163 | 18897 | 391770.8941 | 305873.2658 | 18964 | 393383.5687 | 307843.2017 |
| 18831 | 392384.6734 | 307066.0088 | 18898 | 391679.3170 | 305729.3272 | 18965 | 393402.8222 | 307848.4697 |
| 18832 | 392313.3437 | 306913.9684 | 18899 | 391553.1050 | 305724.3590 | 18966 | 393467.6264 | 307828.7851 |
| 18833 | 392316.6033 | 306891.3546 | 18900 | 391544.8115 | 305746.1195 | 18967 | 393488.1550 | 307741.8312 |
| 18834 | 392291.7009 | 306853.9510 | 18901 | 391563.1234 | 305861.6604 | 18968 | 393478.8820 | 307715.7508 |
| 18835 | 392247.0926 | 306825.0915 | 18902 | 391539.1826 | 305901.3150 | 18969 | 393416.5793 | 307665.4966 |
| 18836 | 392213.9941 | 306814.9327 | 18903 | 391480.2943 | 305908.5861 | 18970 | 393421.4943 | 307629.5779 |
| 18837 | 392209.5212 | 306824.3024 | 18904 | 391436.2198 | 305945.8730 | 18971 | 393502.9552 | 307603.1079 |
| 18838 | 392217.1143 | 306833.5159 | 18905 | 391286.7288 | 305952.9739 | 18972 | 393576.1266 | 307647.8872 |
| 18839 | 392243.3291 | 306847.7073 | 18906 | 391426.1557 | 306147.8889 | 18973 | 393651.0198 | 307643.0046 |
| 18840 | 392255.3933 | 306861.7871 | 18907 | 391499.6049 | 306283.7587 | 18974 | 393675.5660 | 307666.6387 |
| 18841 | 392253.9071 | 306868.6962 | 18908 | 391571.8686 | 306265.1412 | 18975 | 393685.4372 | 307686.2827 |
| 18842 | 392164.6258 | 306921.4982 | 18909 | 391682.9383 | 306382.3127 | 18976 | 393719.6060 | 307711.6958 |
| 18843 | 392107.5485 | 306865.8604 | 18910 | 391668.6183 | 306393.5412 | 18977 | 393753.8206 | 307820.4784 |
| 18844 | 392140.1160 | 306795.5382 | 18911 | 391573.1520 | 306385.5248 | 18978 | 393759.5676 | 307830.8724 |
| 18845 | 392019.4984 | 306791.5867 | 18912 | 391562.5251 | 306419.7595 | 18979 | 393850.1585 | 307821.3709 |
| 18846 | 392009.2290 | 306770.6627 | 18913 | 391644.8978 | 306481.8410 | 18980 | 393869.4887 | 307829.5843 |
| 18847 | 392040.2840 | 306720.9907 | 18914 | 391679.4169 | 306534.4944 | 18981 | 393841.1631 | 307843.2808 |
| 18848 | 391961.4826 | 306681.3720 | 18915 | 391672.0464 | 306565.4075 | 18982 | 393825.3243 | 307894.1516 |
| 18849 | 391956.5039 | 306682.1915 | 18916 | 391646.0635 | 306591.0911 | 18983 | 393819.2604 | 307913.6275 |
| 18850 | 391913.4548 | 306732.1576 | 18917 | 391639.1522 | 306638.8371 | 18984 | 393847.3859 | 307943.0061 |
| 18851 | 391853.0132 | 306751.6028 | 18918 | 391636.1852 | 306746.3697 | 18985 | 393879.2757 | 307958.6032 |
| 18852 | 391790.8758 | 306717.6825 | 18919 | 391748.8760 | 306852.9666 | 18986 | 393922.1809 | 307992.2440 |
| 18853 | 391809.5834 | 306692.5173 | 18920 | 391856.8864 | 306954.8689 | 18987 | 393989.0491 | 308002.6968 |
| 18854 | 391799.3616 | 306662.0943 | 18921 | 391918.0184 | 306972.8802 | 18988 | 394010.3722 | 308038.1389 |
| 18855 | 391743.8538 | 306634.7317 | 18922 | 391977.9673 | 306922.9384 | 18989 | 394036.8506 | 308126.8758 |
| 18856 | 391723.9833 | 306601.8134 | 18923 | 392050.0234 | 306894.8903 | 18990 | 394069.9987 | 308152.9360 |
| 18857 | 391827.2932 | 306599.5673 | 18924 | 392076.9833 | 306926.8879 | 18991 | 394104.9205 | 308149.0514 |
| 18858 | 391800.9296 | 306435.7275 | 18925 | 392108.2215 | 306932.2675 | 18992 | 394245.4148 | 308244.2771 |
| 18859 | 391710.8952 | 306411.8525 | 18926 | 392157.2486 | 306964.5937 | 18993 | 394388.1592 | 308289.8970 |
| 18860 | 391708.7355 | 306380.0665 | 18927 | 392163.6462 | 306982.8645 | 18994 | 394460.9565 | 308259.7117 |
| 18861 | 391820.1057 | 306341.9552 | 18928 | 392153.3104 | 306999.6584 | 18995 | 394460.2720 | 308245.4891 |
| 18862 | 391934.7947 | 306360.0549 | 18929 | 392077.0104 | 307026.8830 | 18996 | 394406.5489 | 308226.3649 |
| 18863 | 392060.6677 | 306405.7510 | 18930 | 392074.0630 | 307085.6508 | 18997 | 394414.0110 | 308162.0096 |
| 18864 | 392042.1545 | 306318.0020 | 18931 | 392106.9073 | 307116.4678 | 18998 | 394483.4106 | 308148.4252 |
| 18865 | 392086.8797 | 306342.1818 | 18932 | 392291.4495 | 307355.4885 | 18999 | 394504.3952 | 308214.0891 |
| 18866 | 392122.2076 | 306413.9888 | 18933 | 392310.7974 | 307541.6788 | 19000 | 394534.8886 | 308203.6509 |
| 18867 | 392213.3491 | 306511.0770 | 18934 | 392347.8033 | 307634.2779 | 19001 | 394571.1828 | 308201.7865 |
| 18868 | 392263.8540 | 306515.4241 | 18935 | 392371.4848 | 307642.1871 | 19002 | 394660.9315 | 308122.9834 |
| 18869 | 392301.5432 | 306467.8111 | 18936 | 392392.0527 | 307620.3401 | 19003 | 394668.1717 | 308126.9627 |
| 18870 | 392276.0014 | 306320.3652 | 18937 | 392410.4621 | 307632.7322 | 19004 | 394692.7495 | 308195.1794 |
| 18871 | 392173.0893 | 306237.4055 | 18938 | 392423.9271 | 307666.4357 | 19005 | 394683.6263 | 308229.9312 |
| 18872 | 392133.4118 | 306227.5247 | 18939 | 392467.2169 | 307688.5019 | 19006 | 394655.1749 | 308248.5299 |

Anexa nr.1 (continuare)

| Nr. crt. | Coordonate | | Nr. crt. | Coordonate | | Nr. crt. | Coordonate | |
|----------|-------------|-------------|----------|-------------|-------------|----------|-------------|-------------|
| | X | Y | | X | Y | | X | Y |
| 19007 | 394608.2481 | 308266.8712 | 19074 | 397083.7110 | 310361.5411 | 19142 | 392432.0919 | 308793.2312 |
| 19008 | 394614.5398 | 308296.7482 | 19075 | 397125.6897 | 310449.5213 | 19143 | 392425.1082 | 308276.0661 |
| 19009 | 394638.3863 | 308298.2820 | 19076 | 397242.9905 | 310541.5017 | 19144 | 392277.7849 | 308109.6315 |
| 19010 | 394653.9554 | 308284.8800 | 19077 | 397297.0934 | 310561.2357 | 19145 | 391938.5843 | 307769.7516 |
| 19011 | 394676.1198 | 308310.7294 | 19078 | 397291.5519 | 310590.8496 | 19146 | 391812.0299 | 307555.5395 |
| 19012 | 394699.0295 | 308309.0937 | 19079 | 397421.5228 | 310680.2399 | 19147 | 391535.8226 | 307350.9793 |
| 19013 | 394746.6174 | 308243.5424 | 19080 | 397509.5499 | 310799.3175 | 19148 | 391365.1367 | 307128.2622 |
| 19014 | 394768.5786 | 308148.5110 | 19081 | 397185.8882 | 310979.6301 | 19149 | 391070.3462 | 306793.8625 |
| 19015 | 394753.6216 | 308081.1471 | 19082 | 397063.0873 | 311189.2881 | 19150 | 390669.6903 | 306313.0310 |
| 19016 | 394917.6014 | 308174.3712 | 19083 | 396793.9363 | 311438.2177 | 19151 | 390642.0628 | 306419.1580 |
| 19017 | 394934.6353 | 308173.2396 | 19084 | 396593.0776 | 311521.7301 | 19152 | 390438.1672 | 306251.1298 |
| 19018 | 394929.7711 | 308120.7900 | 19085 | 396547.5822 | 311582.4601 | 19153 | 390417.8646 | 306173.9695 |
| 19019 | 395045.2518 | 308176.6826 | 19086 | 396297.0583 | 311634.9757 | 19154 | 390413.7197 | 306098.7495 |
| 19020 | 394956.3799 | 308326.5904 | 19087 | 396150.9430 | 311589.3667 | 19155 | 390321.3576 | 306032.3844 |
| 19021 | 394955.5984 | 308338.0453 | 19088 | 395981.5616 | 311552.6132 | 19156 | 390181.9278 | 305929.8888 |
| 19022 | 395016.0228 | 308391.1289 | 19089 | 395768.2811 | 311567.8715 | 19157 | 390098.3624 | 305736.5010 |
| 19023 | 395108.9173 | 308414.1705 | 19090 | 395569.4057 | 311431.7767 | 19158 | 389990.6601 | 305704.8811 |
| 19024 | 395136.4706 | 308370.4423 | 19091 | 395355.6179 | 311376.8957 | 19159 | 389981.8430 | 305822.8929 |
| 19025 | 395220.8493 | 308396.1129 | 19092 | 395173.3147 | 311342.3275 | 19160 | 389918.7837 | 305892.4561 |
| 19026 | 395217.8272 | 308419.4750 | 19093 | 395049.6695 | 311302.4694 | 19161 | 389969.0984 | 305929.2711 |
| 19027 | 395140.8322 | 308416.0875 | 19094 | 395006.3285 | 311302.4694 | 19162 | 389936.3657 | 306059.1253 |
| 19028 | 395137.9774 | 308421.8281 | 19095 | 394969.4488 | 311278.5746 | 19163 | 389876.2389 | 306140.1763 |
| 19029 | 395141.9053 | 308436.9160 | 19096 | 394885.3305 | 311150.0127 | 19164 | 389758.8870 | 306209.0569 |
| 19030 | 395141.0388 | 308497.1561 | 19097 | 394843.3959 | 311022.2424 | 19165 | 389730.6809 | 306302.1183 |
| 19031 | 395194.8216 | 308576.3099 | 19098 | 394783.1865 | 310829.0079 | 19166 | 389672.4889 | 306210.0959 |
| 19032 | 395213.0411 | 308656.4070 | 19099 | 394770.3029 | 310651.5845 | 19167 | 389533.4777 | 306126.0957 |
| 19033 | 395321.3790 | 308812.3209 | 19101 | 394644.5484 | 310688.7921 | 19168 | 389273.5263 | 306102.7051 |
| 19034 | 395358.0126 | 308805.7892 | 19102 | 394489.3465 | 310795.1378 | 19169 | 389167.1389 | 306056.6550 |
| 19035 | 395352.7770 | 308750.7886 | 19103 | 394327.8033 | 310862.4793 | 19170 | 389098.9755 | 305938.1589 |
| 19036 | 395387.7476 | 308688.7533 | 19104 | 394223.3262 | 310799.6699 | 19171 | 389057.7121 | 305909.3586 |
| 19037 | 395413.8473 | 308693.4614 | 19105 | 394150.4690 | 310794.2426 | 19172 | 388984.5737 | 305892.2978 |
| 19038 | 395500.1695 | 308759.9736 | 19106 | 393859.8728 | 310846.7977 | 19173 | 388851.5972 | 305941.0770 |
| 19039 | 395540.0420 | 308773.4286 | 19107 | 393809.4965 | 310830.1178 | 19174 | 388725.1520 | 305932.1807 |
| 19040 | 395555.3367 | 308845.9878 | 19108 | 393531.0737 | 310917.4485 | 19175 | 388645.0931 | 305983.8932 |
| 19041 | 395550.4469 | 308936.9596 | 19109 | 393504.0838 | 310947.5110 | 19176 | 388600.4261 | 306073.8566 |
| 19042 | 395565.3528 | 308965.7723 | 19110 | 393225.1300 | 311009.0922 | 19177 | 388567.1339 | 306087.1851 |
| 19043 | 395645.7167 | 308976.0588 | 19111 | 393136.5246 | 311177.2946 | 19178 | 388396.4431 | 306006.6317 |
| 19044 | 395669.2074 | 308925.2349 | 19112 | 393005.2857 | 311088.1806 | 19179 | 388361.9540 | 305962.2137 |
| 19045 | 395705.9261 | 308915.7963 | 19113 | 392948.0464 | 311049.3139 | 19180 | 388323.5228 | 305962.2137 |
| 19046 | 395741.6719 | 308928.5906 | 19114 | 392872.0485 | 311071.0969 | 19181 | 388137.1480 | 306072.1025 |
| 19047 | 395759.6828 | 309019.1845 | 19115 | 392833.9548 | 311001.9933 | 19182 | 388086.0920 | 306084.5866 |
| 19048 | 395748.8974 | 309138.0480 | 19116 | 392872.8979 | 310930.0422 | 19183 | 388008.6132 | 306131.4648 |
| 19049 | 395658.1433 | 309079.6100 | 19117 | 393032.4810 | 310898.7038 | 19184 | 387764.4865 | 306068.8067 |
| 19050 | 395603.3483 | 309060.1032 | 19118 | 393014.0870 | 310676.1872 | 19185 | 387510.2221 | 305929.1295 |
| 19051 | 395565.4649 | 309113.2761 | 19119 | 393360.9926 | 310647.3014 | 19186 | 387348.9904 | 305937.4779 |
| 19052 | 395736.0967 | 309243.9495 | 19120 | 393466.8870 | 310432.1146 | 19187 | 387247.4431 | 305958.1708 |
| 19053 | 396126.2729 | 309652.0801 | 19121 | 393765.5203 | 310294.5979 | 19188 | 387164.8178 | 305979.3008 |
| 19054 | 396355.0819 | 309786.7760 | 19122 | 393713.7151 | 310044.9277 | 19189 | 387050.2086 | 305967.0302 |
| 19055 | 396434.7537 | 309885.4002 | 19123 | 394049.7233 | 310248.7651 | 19190 | 386953.7360 | 306007.7584 |
| 19056 | 396538.7116 | 309936.1929 | 19124 | 394159.0501 | 310321.4824 | 19191 | 386788.8171 | 305892.6519 |
| 19057 | 396566.8639 | 309974.1069 | 19125 | 394248.0962 | 310228.4659 | 19192 | 386683.4619 | 305769.3237 |
| 19058 | 396613.1628 | 309959.7062 | 19126 | 394168.5259 | 310118.7489 | 19193 | 386648.2096 | 305750.6048 |
| 19059 | 396677.0618 | 310043.4378 | 19127 | 394358.9261 | 309892.9108 | 19194 | 386452.4352 | 305709.5119 |
| 19060 | 396723.8529 | 310066.9989 | 19128 | 393915.9329 | 309468.9259 | 19195 | 386381.1690 | 305640.1190 |
| 19061 | 396787.2329 | 310055.6974 | 19129 | 393885.9715 | 309488.9512 | 19196 | 386249.0422 | 305640.0486 |
| 19062 | 396790.6107 | 310082.2091 | 19130 | 393755.5743 | 309525.6672 | 19197 | 385974.9366 | 305727.5429 |
| 19063 | 396814.1450 | 310135.4388 | 19131 | 393589.0667 | 309449.4989 | 19198 | 385828.2389 | 305809.3647 |
| 19064 | 396781.2004 | 310165.2557 | 19132 | 393489.5431 | 309289.1375 | 19199 | 385698.6858 | 305573.3683 |
| 19065 | 396785.8883 | 310182.9101 | 19133 | 393409.4516 | 309142.5558 | 19201 | 385723.2664 | 305487.8318 |
| 19066 | 396838.0721 | 310211.6011 | 19134 | 393301.0001 | 309036.1892 | 19202 | 385781.3420 | 305507.1391 |
| 19067 | 396878.6761 | 310220.7220 | 19135 | 393193.4019 | 309139.0059 | 19203 | 385789.4770 | 305420.7928 |
| 19068 | 396900.2992 | 310278.1679 | 19136 | 393048.5559 | 309155.7796 | 19204 | 385730.9692 | 305279.0232 |
| 19069 | 396916.7271 | 310286.6091 | 19137 | 392873.4652 | 309136.0463 | 19205 | 385674.7118 | 305184.8098 |
| 19070 | 396955.3798 | 310288.8230 | 19138 | 392866.7292 | 309152.5725 | 19206 | 385548.0769 | 305156.0113 |
| 19071 | 396971.3782 | 310329.1289 | 19139 | 392763.5497 | 309123.6968 | 19207 | 385458.1113 | 304974.4828 |
| 19072 | 396974.8520 | 310360.4132 | 19140 | 392731.0617 | 309143.9392 | 19208 | 385340.1192 | 304827.4078 |
| 19073 | 397056.2806 | 310366.2491 | 19141 | 392585.0022 | 309046.9342 | 19209 | 385283.5876 | 304848.2966 |

Anexa nr.1 (continuare)

| Nr. crt. | Coordonate | | Nr. crt. | Coordonate | | Nr. crt. | Coordonate | |
|----------|--------------------------|-------------|----------|-------------|-------------|----------|-------------|-------------|
| | X | Y | | X | Y | | X | Y |
| 19210 | 385269.8888 | 304821.4068 | 19276 | 396164.0149 | 308952.7568 | 19344 | 396314.3849 | 309392.7496 |
| 19211 | 385278.6728 | 304708.9857 | 19277 | 396174.8510 | 308953.6601 | 19345 | 396335.4153 | 309373.8075 |
| 19212 | 385293.5400 | 304600.3873 | 19278 | 396230.6352 | 308947.7714 | 19346 | 396335.7453 | 309357.0785 |
| 19213 | 385340.6597 | 304632.0778 | 19279 | 396268.8719 | 308932.2697 | 19347 | 396297.0253 | 309308.9181 |
| 19214 | 385344.6460 | 304614.5603 | 19280 | 396281.9839 | 308910.0800 | 19348 | 396274.0243 | 309294.3373 |
| 19215 | 385250.6300 | 304494.8489 | 19281 | 396284.3339 | 308908.8183 | 19349 | 396241.6458 | 309301.2747 |
| 19216 | 385234.7115 | 304507.5323 | 19282 | 396288.9563 | 308908.8183 | 19350 | 396205.1693 | 309321.6854 |
| 19217 | 385250.1043 | 304569.4173 | 19283 | 396305.3709 | 308919.2306 | 19351 | 396186.5244 | 309317.5290 |
| 19218 | 385234.4002 | 304611.2836 | 19284 | 396310.9477 | 308921.7094 | 19352 | 396182.6787 | 309309.2487 |
| 19219 | 385217.4036 | 304680.1356 | 19285 | 396336.1715 | 308936.2537 | 19353 | 396187.0553 | 309257.4775 |
| 19220 | 385183.5995 | 304690.1756 | 19286 | 396316.2908 | 309005.3137 | 19354 | 396176.3812 | 309242.9333 |
| 19221 | 385173.6374 | 304681.9064 | 19287 | 396317.6528 | 309030.8118 | 19355 | 396156.5061 | 309239.8905 |
| 19222 | 385160.8624 | 304655.9968 | 19288 | 396330.2741 | 309048.0581 | 19356 | 396123.2265 | 309263.0174 |
| 19223 | 385154.1971 | 304576.0126 | 19289 | 396358.6228 | 309058.1802 | 19357 | 396116.8598 | 309263.0174 |
| 19224 | 385149.7669 | 304500.1840 | 19290 | 396407.7683 | 309065.8724 | 19358 | 396093.0709 | 309243.5925 |
| 19225 | 385154.2701 | 304489.6011 | 19291 | 396399.0339 | 309097.0249 | 19359 | 396054.3959 | 309195.1594 |
| 19226 | 385169.0018 | 304474.1743 | 19292 | 396397.4753 | 309103.0622 | 19360 | 396027.1360 | 309172.6703 |
| 19227 | 385232.5433 | 304460.1661 | 19293 | 396395.4453 | 309164.3244 | 19361 | 395997.7357 | 309140.5938 |
| 19228 | 385240.3447 | 304444.0348 | 19294 | 396451.6190 | 309280.2276 | 19362 | 395993.8947 | 309132.3764 |
| 19229 | 385229.5294 | 304427.5093 | 19295 | 396468.8088 | 309303.5987 | 19363 | 395992.9010 | 309117.9883 |
| 19230 | 385203.5401 | 304408.7767 | 19296 | 396487.7050 | 309313.0001 | 19364 | 395994.5986 | 309105.8924 |
| 19231 | 385165.7585 | 304383.4068 | 19297 | 396541.5861 | 309299.7026 | 19365 | 396026.4162 | 309041.8204 |
| 19232 | 385154.7183 | 304382.1982 | 19298 | 396567.0878 | 309265.7171 | 19366 | 396025.3492 | 309016.9335 |
| 19233 | 385146.8596 | 304387.6960 | 19299 | 396563.9317 | 309206.5188 | 19367 | 396020.9890 | 309001.2364 |
| 19234 | 385126.9242 | 304424.8757 | 19301 | 396580.4683 | 309206.5188 | 19368 | 395984.2311 | 308936.7344 |
| 19235 | 385100.9885 | 304432.7636 | 19302 | 396586.8925 | 309232.0850 | 19369 | 395920.6808 | 308879.7987 |
| 19236 | 385081.1223 | 304426.0907 | 19303 | 396595.5534 | 309279.5179 | 19370 | 395853.4008 | 308858.5827 |
| 19237 | 385060.9986 | 304407.7006 | 19304 | 396604.4525 | 309317.0531 | 19371 | 395828.9557 | 308861.9054 |
| 19238 | 385057.7077 | 304393.2223 | 19305 | 396611.8556 | 309373.9878 | 19372 | 395811.4419 | 308873.8532 |
| 19239 | 385069.7471 | 304370.7687 | 19306 | 396620.4336 | 309429.4341 | 19373 | 395780.3449 | 308873.6970 |
| 19240 | 385101.2104 | 304346.2034 | 19307 | 396625.0801 | 309446.4257 | 19374 | 395762.4637 | 308867.9401 |
| 19241 | 385123.5960 | 304304.8509 | 19308 | 396632.9020 | 309463.7024 | 19375 | 395738.3747 | 308848.8155 |
| 19242 | 385125.0315 | 304279.9237 | 19309 | 396663.1036 | 309551.4103 | 19376 | 395732.2127 | 308834.1252 |
| 19243 | 385120.2873 | 304274.9893 | 19310 | 396657.1181 | 309583.2057 | 19377 | 395731.7640 | 308819.2117 |
| 19244 | 385102.1693 | 304267.8607 | 19311 | 396637.0511 | 309639.7088 | 19378 | 395629.8453 | 308717.4646 |
| 19245 | 385078.2775 | 304267.9338 | 19312 | 396647.0789 | 309663.2252 | 19379 | 395516.7897 | 308590.5641 |
| | parcelele 129-133 | | 19313 | 396665.0016 | 309685.6680 | 19380 | 395483.2763 | 308543.8885 |
| 19246 | 395314.4870 | 308176.4414 | 19314 | 396676.2905 | 309715.1391 | 19381 | 395438.1354 | 308519.5345 |
| 19247 | 395328.0795 | 308179.3158 | 19315 | 396670.0620 | 309739.3427 | 19382 | 395424.9626 | 308498.6207 |
| 19248 | 395361.3096 | 308209.6438 | 19316 | 396646.5909 | 309767.7470 | 19383 | 395418.1491 | 308498.6207 |
| 19249 | 395368.2035 | 308223.2468 | 19317 | 396622.1306 | 309802.7008 | 19384 | 395360.2916 | 308517.3559 |
| 19250 | 395422.7528 | 308265.9344 | 19318 | 396572.0541 | 309798.2327 | 19385 | 395284.0098 | 308508.8727 |
| 19251 | 395483.3623 | 308292.9620 | 19319 | 396523.7768 | 309797.3225 | 19386 | 395235.4373 | 308468.9702 |
| 19252 | 395669.1654 | 308365.3833 | 19320 | 396442.2522 | 309782.2562 | 19387 | 395276.9841 | 308431.4736 |
| 19253 | 395692.1186 | 308385.0231 | 19321 | 396401.5750 | 309762.6872 | 19388 | 395310.9498 | 308407.4461 |
| 19254 | 395712.0105 | 308448.5494 | 19322 | 396396.8200 | 309754.8489 | 19389 | 395315.9396 | 308394.2690 |
| 19255 | 395743.3748 | 308500.1076 | 19323 | 396411.1378 | 309738.2245 | 19390 | 395309.2065 | 308351.3177 |
| 19256 | 395787.9530 | 308546.9942 | 19324 | 396471.6817 | 309696.4769 | 19391 | 395309.9879 | 308347.3500 |
| 19257 | 395815.6951 | 308572.4355 | 19325 | 396431.4930 | 309588.6642 | 19392 | 395316.9903 | 308336.1020 |
| 19258 | 395889.0370 | 308619.9996 | 19326 | 396433.5872 | 309550.0038 | 19393 | 395338.7433 | 308316.3566 |
| 19259 | 395985.0742 | 308660.5045 | 19327 | 396438.6250 | 309549.5024 | 19394 | 395342.6600 | 308292.8099 |
| 19260 | 396003.5135 | 308673.9392 | 19328 | 396499.5381 | 309569.3967 | 19395 | 395333.4248 | 308273.9510 |
| 19261 | 396018.9129 | 308698.4170 | 19329 | 396526.4904 | 309574.0625 | 19396 | 395331.4540 | 308244.9091 |
| 19262 | 396025.9788 | 308702.9507 | 19330 | 396532.5557 | 309568.3491 | 19397 | 395322.1325 | 308222.4091 |
| 19263 | 396036.5454 | 308702.9507 | 19331 | 396532.4844 | 309548.2809 | 19398 | 395308.4615 | 308198.8806 |
| 19264 | 396069.2642 | 308696.1167 | 19332 | 396515.7274 | 309536.7005 | 19399 | 395304.6074 | 308189.9755 |
| 19265 | 396097.7157 | 308702.2630 | 19333 | 396520.4831 | 309520.6298 | 19400 | 395304.6074 | 308185.2065 |
| 19266 | 396132.0872 | 308717.6552 | 19334 | 396514.3247 | 309510.6068 | 19401 | 395310.0029 | 308177.8431 |
| 19267 | 396148.2961 | 308736.8854 | 19335 | 396496.8685 | 309501.2305 | 19402 | 395314.4870 | 308176.4414 |
| 19268 | 396159.4189 | 308774.7330 | 19336 | 396497.6635 | 309475.7680 | | | |
| | parcela 155 | | | | | | | |
| 19269 | 396161.9858 | 308844.8904 | 19337 | 396492.1241 | 309465.7958 | 19403 | 394485.8274 | 307767.5628 |
| 19270 | 396157.7756 | 308854.4182 | 19338 | 396443.7690 | 309458.0342 | 19404 | 394516.7168 | 307796.1950 |
| 19271 | 396125.2821 | 308894.4809 | 19339 | 396408.4614 | 309426.7066 | 19405 | 394569.7951 | 307889.1307 |
| 19272 | 396120.4082 | 308904.4246 | 19340 | 396339.5881 | 309427.9601 | 19406 | 394584.2460 | 307904.1115 |
| 19273 | 396119.1902 | 308914.2749 | 19341 | 396309.2212 | 309433.3843 | 19407 | 394549.5556 | 307913.5725 |
| 19274 | 396125.3765 | 308933.9757 | 19342 | 396300.6157 | 309425.4772 | 19408 | 394549.5556 | 307910.4141 |
| 19275 | 396138.3744 | 308945.6050 | 19343 | 396305.0755 | 309407.2330 | 19409 | 394522.3088 | 307878.8628 |

Anexa nr.1 (continuare)

| Nr. crt. | Coordonate | | Nr. crt. | Coordonate | | Nr. crt. | Coordonate | |
|-------------------|-------------|-------------|----------|-------------|-------------|-----------------------------------|-------------|-------------|
| | X | Y | | X | Y | | X | Y |
| 19410 | 394485.6993 | 307820.2471 | 19474 | 391649.0851 | 309503.4897 | 19541 | 391621.2900 | 310103.1247 |
| 19411 | 394485.6993 | 307769.3937 | 19475 | 391665.4612 | 309476.6626 | 19542 | 391583.1565 | 309953.5498 |
| parcela 156 | | | 19476 | 391672.1883 | 309474.1821 | 19543 | 391585.8991 | 309860.4946 |
| 19412 | 394249.0285 | 307811.5347 | 19477 | 391689.3416 | 309474.1821 | 19544 | 391549.6258 | 309795.2633 |
| 19413 | 394282.7627 | 307840.7490 | 19478 | 391701.4247 | 309476.4661 | 19545 | 391508.3770 | 309798.4858 |
| 19414 | 394378.7303 | 307839.3962 | 19479 | 391725.4314 | 309471.7180 | 19546 | 391442.9539 | 309739.4660 |
| 19415 | 394410.0873 | 307897.2106 | 19480 | 391752.5458 | 309508.6055 | 19547 | 391427.6215 | 309553.2162 |
| 19416 | 394499.2817 | 307938.2762 | 19481 | 391739.9789 | 309528.7480 | 19548 | 391491.6608 | 309355.3119 |
| 19417 | 394570.7223 | 307987.2095 | 19482 | 391745.0000 | 309559.9921 | 19549 | 391559.5426 | 309105.5124 |
| 19418 | 394575.0279 | 308026.5967 | 19483 | 391738.7884 | 309595.4085 | 19550 | 391599.5133 | 309044.2518 |
| 19419 | 394553.8049 | 308082.7291 | 19484 | 391709.0745 | 309615.4039 | 19551 | 391618.0464 | 309002.9662 |
| 19420 | 394517.8901 | 308110.5316 | 19485 | 391724.5904 | 309628.0236 | 19552 | 391618.0464 | 308974.6947 |
| 19421 | 394419.0533 | 308073.0938 | 19486 | 391776.7525 | 309696.3719 | 19553 | 391549.0514 | 308947.1524 |
| 19422 | 394311.5119 | 308090.1169 | 19487 | 391845.3069 | 309733.4428 | parcela 128 | | |
| 19423 | 394309.3451 | 307982.4019 | 19488 | 391894.2283 | 309743.1228 | 19554 | 396232.7721 | 309672.7890 |
| 19424 | 394324.0208 | 307912.7408 | 19489 | 391932.3213 | 309735.0615 | 19555 | 396261.7985 | 309669.2087 |
| 19425 | 394265.1833 | 307877.3170 | 19490 | 391937.6626 | 309738.2686 | 19556 | 396314.9625 | 309684.6313 |
| parcela 157 | | | 19491 | 391925.5293 | 309752.2450 | 19557 | 396376.5769 | 309664.9590 |
| 19426 | 394076.5197 | 307734.0641 | 19492 | 391927.2081 | 309755.5291 | 19558 | 396407.9737 | 309671.7522 |
| 19427 | 394083.7716 | 307745.7706 | 19493 | 391954.0016 | 309761.0690 | 19559 | 396406.1206 | 309712.1643 |
| 19428 | 394090.7114 | 307771.9139 | 19494 | 391965.6049 | 309765.3613 | 19560 | 396397.8304 | 309725.6351 |
| 19429 | 394083.8492 | 307799.6984 | 19495 | 391991.2729 | 309788.6444 | 19561 | 396357.9404 | 309747.6200 |
| 19430 | 394069.7500 | 307826.1501 | 19496 | 391996.7751 | 309804.2109 | 19562 | 396232.7721 | 309679.9475 |
| 19431 | 394030.5923 | 307835.3676 | 19497 | 392004.1111 | 309814.1772 | 19563 | 396232.7721 | 309672.7890 |
| 19432 | 394022.9169 | 307835.3676 | 19498 | 392034.3108 | 309837.7606 | parcelele 204-207, 209, 210, 212% | | |
| 19433 | 394011.9641 | 307826.0446 | 19499 | 392031.3925 | 309850.0473 | 19564 | 389507.2261 | 303074.7016 |
| 19434 | 394016.6212 | 307803.4308 | 19500 | 392023.2365 | 309854.6864 | 19565 | 389670.1798 | 303068.4751 |
| 19435 | 394016.2669 | 307774.9851 | 19501 | 392013.0036 | 309867.1597 | 19566 | 389815.3379 | 303017.6601 |
| 19436 | 394041.8601 | 307732.3967 | 19502 | 392013.0036 | 309874.4623 | 19567 | 389815.3458 | 303101.7275 |
| 19437 | 394052.0295 | 307728.4512 | 19503 | 392022.0167 | 309889.1548 | 19568 | 389673.0078 | 303127.3829 |
| 19438 | 394069.2424 | 307729.6947 | 19504 | 392026.3091 | 309891.7330 | 19569 | 389664.3864 | 303201.7612 |
| 19439 | 394076.5197 | 307734.0641 | 19505 | 392037.2974 | 309891.7330 | 19570 | 389717.7672 | 303272.9672 |
| parcelele 163-166 | | | 19506 | 392108.8263 | 309871.7096 | 19571 | 389803.7899 | 303449.0909 |
| 19440 | 391549.0514 | 308947.1524 | 19507 | 392138.1764 | 309877.9006 | 19572 | 389907.7803 | 303369.5228 |
| 19441 | 391587.4974 | 308918.7515 | 19508 | 392172.7228 | 309870.2512 | 19573 | 390118.9812 | 303347.2864 |
| 19442 | 391672.6874 | 308879.5103 | 19509 | 392192.0381 | 309871.1964 | 19574 | 390196.3966 | 303378.9731 |
| 19443 | 391766.0979 | 308875.1947 | 19510 | 392232.5129 | 309888.0756 | 19575 | 390093.3123 | 303445.1196 |
| 19444 | 391815.3484 | 308892.8551 | 19511 | 392232.2044 | 309905.0157 | 19576 | 390297.2731 | 303672.9036 |
| 19445 | 391858.1274 | 308930.2201 | 19512 | 392221.3835 | 309920.0996 | 19577 | 390374.2189 | 303747.1045 |
| 19446 | 391886.4566 | 309017.8413 | 19513 | 392175.2365 | 309955.1238 | 19578 | 390378.0059 | 303786.4443 |
| 19447 | 391879.0270 | 309059.6732 | 19514 | 392161.6336 | 309971.2909 | 19579 | 390417.3158 | 303899.4292 |
| 19448 | 391853.0478 | 309117.3597 | 19515 | 392160.1651 | 309984.5188 | 19580 | 390577.8175 | 303949.1150 |
| 19449 | 391771.1394 | 309141.6364 | 19516 | 392165.9616 | 309989.3142 | 19581 | 390665.9741 | 304042.2132 |
| 19450 | 391719.7212 | 309174.0739 | 19517 | 392190.3658 | 309997.7447 | 19582 | 390681.8550 | 303978.9917 |
| 19451 | 391740.3523 | 309201.3119 | 19518 | 392231.7043 | 309990.8741 | 19583 | 390818.3576 | 304112.1973 |
| 19452 | 391758.5809 | 309263.7697 | 19519 | 392307.3518 | 309975.3885 | 19584 | 390928.4935 | 304314.7584 |
| 19453 | 391693.3261 | 309337.6297 | 19520 | 392336.1102 | 309917.0670 | 19585 | 390979.9114 | 304360.8618 |
| 19454 | 391702.8197 | 309355.2916 | 19521 | 392385.4448 | 309894.2727 | 19586 | 390962.3546 | 304384.9434 |
| 19455 | 391701.3371 | 309358.3999 | 19522 | 392363.9337 | 309868.4620 | 19587 | 391088.8718 | 304519.2148 |
| 19456 | 391677.5519 | 309377.3313 | 19523 | 392373.3450 | 309844.8523 | 19588 | 391174.6110 | 304460.0925 |
| 19457 | 391673.3694 | 309386.6334 | 19524 | 392377.8665 | 309841.3916 | 19589 | 391240.0111 | 304630.0549 |
| 19458 | 391673.3694 | 309410.5119 | 19525 | 392403.0101 | 309844.0246 | 19590 | 391291.3553 | 304760.8873 |
| 19459 | 391695.2131 | 309421.3650 | 19526 | 392430.6289 | 309826.4314 | 19591 | 391263.5499 | 304798.1502 |
| 19460 | 391751.0650 | 309422.3820 | 19527 | 392445.9536 | 309808.2743 | 19592 | 391289.6276 | 304897.1849 |
| 19461 | 391754.0577 | 309433.1184 | 19528 | 392447.4502 | 309797.2554 | 19593 | 391392.0790 | 304872.5416 |
| 19462 | 391750.0902 | 309434.7125 | 19529 | 392475.1148 | 309798.6571 | 19594 | 391434.2066 | 304886.5672 |
| 19463 | 391707.1308 | 309439.9869 | 19530 | 392521.3039 | 309767.6880 | 19595 | 391431.7607 | 304909.3577 |
| 19464 | 391668.7672 | 309451.3967 | 19531 | 392562.1199 | 309775.8791 | 19596 | 391470.3072 | 304935.8832 |
| 19465 | 391657.5332 | 309449.6213 | 19532 | 392601.9123 | 309810.7734 | 19597 | 391511.2425 | 305000.7613 |
| 19466 | 391652.2335 | 309444.4819 | 19533 | 392501.5007 | 309875.7748 | 19598 | 391484.8200 | 305166.5859 |
| 19467 | 391652.0071 | 309415.5846 | 19534 | 392357.6539 | 310132.4677 | 19599 | 391484.8200 | 305245.3810 |
| 19468 | 391644.4573 | 309401.5053 | 19535 | 392265.0477 | 310236.5341 | 19600 | 391527.2957 | 305333.9336 |
| 19469 | 391630.7910 | 309398.6646 | 19536 | 392004.5925 | 310459.0461 | 19601 | 391512.3535 | 305369.5291 |
| 19470 | 391621.7731 | 309410.2139 | 19537 | 391957.8312 | 310398.9473 | 19602 | 391471.7282 | 305393.7892 |
| 19471 | 391640.2700 | 309466.5502 | 19538 | 391922.0260 | 310363.1125 | 19603 | 391289.6855 | 305414.9867 |
| 19472 | 391640.2700 | 309494.9375 | 19539 | 391786.9841 | 310310.8331 | 19604 | 391129.9270 | 305427.2219 |
| 19473 | 391646.1684 | 309504.3343 | 19540 | 391671.7371 | 310219.2954 | 19605 | 391103.9693 | 305319.3551 |

Anexa nr.1 (continuare)

| Nr. crt. | Coordonate | | Nr. crt. | Coordonate | | Nr. crt. | Coordonate | |
|-------------|-------------|-------------|-------------|-------------|-------------|-------------|-------------|-------------|
| | X | Y | | X | Y | | X | Y |
| 19606 | 391239.3045 | 305342.4746 | 19617 | 390570.3170 | 304594.6455 | 19628 | 390252.5490 | 303827.4498 |
| 19607 | 391373.9855 | 305209.6654 | 19618 | 390503.5897 | 304511.4273 | 19629 | 390135.5665 | 303753.7122 |
| 19608 | 391333.8422 | 305059.1991 | 19619 | 390570.1434 | 304395.0823 | 19630 | 390017.4996 | 303495.6139 |
| 19609 | 391293.3424 | 305043.6685 | 19620 | 390652.2121 | 304283.0924 | 19631 | 389951.0251 | 303525.2286 |
| 19610 | 391072.2169 | 304994.7089 | 19621 | 390517.4780 | 304139.3718 | 19632 | 389815.4597 | 303623.0379 |
| 19611 | 391127.2249 | 304870.1879 | 19622 | 390482.8729 | 304125.3181 | 19633 | 389805.7036 | 303738.4432 |
| 19612 | 391023.7554 | 304612.1487 | 19623 | 390321.3673 | 304255.2892 | 19634 | 389784.5703 | 303735.2654 |
| 19613 | 390931.5300 | 304481.2075 | 19624 | 390281.9867 | 304245.3928 | 19635 | 389642.2351 | 303526.9992 |
| 19614 | 390875.2393 | 304655.3726 | 19625 | 390346.5198 | 304039.2115 | 19636 | 389610.3777 | 303408.3632 |
| 19615 | 390786.6284 | 304776.3447 | 19626 | 390231.1373 | 303989.6130 | 19637 | 389469.2032 | 303282.3177 |
| 19616 | 390638.8298 | 304626.4389 | 19627 | 390204.9638 | 303878.5272 | 19638 | 389507.2261 | 303074.7016 |